



If a generator fails, production can be continued by bridging the generator.

7.8.1 Bridging the generator



WARNING

The machine must be completely switched off before bridging the generator! Completely switched off means the main switch must be locked and secured in the left (or 0) position.



Disconnect both EtherCAT P cables from the generator and connect them with the supplied bridging cable.

Then unplug the power cable " $W_100.xxx$ " first from the corresponding terminals in the control cabinet. After that, it can also be disconnected from the generator.

7.8.2 Re-supply EtherCAT P junction



If more than approx. 5 generators are serially connected, a re-supply EtherCAT P junction (EPP1332) is connected in between.

Depending on which generator failed, the position of the resupply junction must be adjusted.



Generator failure without re-supply junction:

No adjustment necessary



No adjustment necessary





7.8.3 Adjust settings after bridging



CAN MAN

NOTE

4.5

4.5.1

Locked recipes are marked with a "*" symbol.

Service area (login level 1)

Test functions



7070



.

22.0 °C 7.0 %

Different settings for the temperature sensor. Refer to <u>chapter 5.5.</u> to set the sensor correctly.

4.5.2 Service settings



Temperature offset

Temperature scaling

Ð

In this window, the number of 3m units, as well as the number of generators can be set.

These settings must be identical to the configuration of your system.

If a generator is added or removed, the settings must be adjusted.

NOTE

The "Nos. of Generators" in the settings only apply to the generators installed on the PowerCURE. If a pre-heating generator is installed on the exit conveyor of the welder, it must not be added to this value!



If there is a pre-heating generator on the exit conveyor of the welder, the function "Preheating Coil" must be activated.

If the first module is equipped with a lift unit, the function "Lift ON / OFF" must be activated.



The selected configuration must correspond to the values of the settings in <u>chapter 4.5.2</u> and the installed curing system.



generators on each 3m unit can now be selected.



If the function "Preheating Coil" is activated, an additional module (exit conveyor welder) with an additional generator is shown.

	Preneating con Sin On	
4.5.4 Timings	示 C Suction OFF Delay 2.0 min ^W C Welder to PowerCure 0.0 sec	The following parameters can be set in the tab "Timings": Suction OFF Delay: Time how long the fume extraction keeps running after production is stopped. Welder to PowerCure: Time how long the coil continues heating after production is stopped. The value corresponds to the time a canbody needs to get transported from the downstacker of the welder to the entry of the PowerCure.
 4.6 Start / Stop signals NOTE The start / stop of production is controlled by 2 signals 	Enable main switch (MS) ON/OFF	Enable Main switch (MS): - X150_154 - X150_155
connected to the welding machine. NOTE Refer to the electrical diagram in <u>chapter 12.1</u>	Enable curing (HF) ON/OFF	Enable curing (HF): - X150_156 - X150_157
	Error signal	Error signal: - X150_158 - X150_159